

## Howard County Pipe Break Field Data

	Location and Contact information		
Date	12-28-12	Time	700
Crew Leader name	D. Ball	Crew Leader phone #	113
Address	5917 Morning Bird		
ADC page		ADC Grid	
Base Map #		Contract #	385

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

### Size of Pipe

Size in inches	6
----------------	---