

Howard County Pipe Break Field Data

Location and Contact information			
Date	11/16/2012	Time	17:00 pm
Crew Leader name	Mike Fisher	Crew Leader phone #	301-401-3680
Address	5975 Grand Banks Columbia MD 21045		
ADC page	4934	ADC Grid	H5
Base Map #	2739	Contract #	304 w&s

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand	x	Blue/gray clay	
Silt	x		

Pipe Type

Type	Check box	Type	Check box
Cast iron	x	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	x	Damage by others	
Split		Pipe Joint leak	
Pitting		Valve problem	
Fitting leak		Clamp repair	

Size of Pipe

Size in inches	6"
----------------	----