

Howard County Pipe Break Field Data

Location and Contact information			
Date	11/24/2012	Time	9:00 am
Crew Leader name	Chuck Garrett	Crew Leader phone #	410-615-0241
Address	6017 camelback lane Columbia Md 21045		
ADC page	4935	ADC Grid	D7
Base Map #	2541	Contract #	288 w&s

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand	x	Blue/gray clay	
Silt	x		

Pipe Type

Type	Check box	Type	Check box
Cast iron	x	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	x	Damage by others	
Split		Pipe Joint leak	
Pitting		Valve problem	
Fitting leak		Clamp repair	

Size of Pipe

Size in inches	8"
----------------	----