

Howard County Pipe Break Field Data

Location and Contact information			
Date	5/14/2012	Time	12:12 pm
Crew Leader name	Leo Dickey	Crew Leader phone #	
Address	6196 Farstar PL Columbia MD 21046		
ADC page	4935	ADC Grid	H8
Base Map #		Contract #	374 - W & S

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split	<input checked="" type="checkbox"/>	Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	6"
----------------	----