

Howard County Pipe Break Field Data

Location and Contact information			
Date	11-10-12	Time	2:00 PM
Crew Leader name	Tom Pickett	Crew Leader phone #	
Address	6245 Cricket Pass		
ADC page	4934	ADC Grid	J-8
Base Map #	GRID 36-2539	Contract #	488

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	6"
----------------	----