HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY:	12-2	1-10			
TIME:	700				===
TIME OF BREAK:					_
ENGINEER:					
					_
LOCATION:					
GPS LOCATION:	6465	Forrest &	LUP		
					-
					_
GPS:	-				=
	-	о.			
PHOTO BEFORE RI	EPAIRS:				
Number of Pictures:		٠.			٠.
SOIL CHEMISTRIES	:				
REDOX		SOIL BOX RESIS	TIVITES	рН	
	(mV)		(Ohm-cm)		(mV)
	(mV)		(Ohm-cm)		(mV)
Top of Pipe (12)	<u> </u>	Top of Pipe (12)		Top of Pipe (12)	11117
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)	3 4	Bottom of Pipe (6)		Bottom of Pipe (6)	
		5 3 (3)		Actual Soil pH	
Soil Type: Cla	ıy S	and Silt	Clay/sar		Other _
DETAILS.					
Pine Type: // Car	st Iron	Ductile Iron	Steel	PCCP Plast	
Pipe Type : Cas Pipe Size: 8 i7			0.00	_ 1 001 1 1830	
Repair Method:	Clamp	Weld Cut	Oth	ier	,
DETAILS:	_ Olding				
Form of Break: ()	Circular	Longitudinal	Other	1	
DETAILS:	01.041011				
PHOTO AFTER REP.	ΔIRS:				
Number of Pictures:	mic.				
Turribor or Frotaros.			Ī	TESTING VIE	١٨/
SKETCH OF SITE				(LOTING TIL	
SKETCH OF SITE				12	Top
			1	12	
					~~
				9	3
			f		J
					ĺ
				6	
				Clock	