

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 2/23/08
TIME: _____
TIME OF BREAK: 9:00 AM 2/23/08
ENGINEER: Bernie Sensibaugh

LOCATION: _____
GPS LOCATION: 6600 Cradile Rock way (15 J-10)

GPS: _____

PHOTO BEFORE REPAIRS:
 Number of Pictures: 5

SOIL CHEMISTRIES:

REDOX	SOIL BOX RESISTIVITES	pH
(mV)	(Ohm-cm)	(mV)
(mV)	(Ohm-cm)	(mV)
Top of Pipe (12)	Top of Pipe (12)	Top of Pipe (12)
Side of Pipe (3 / 9)	Side of Pipe (3 / 9)	Side of Pipe (3 / 9)
Bottom of Pipe (6)	Bottom of Pipe (6)	Bottom of Pipe (6)
		Actual Soil pH

Soil Type: Clay Sand Silt Clay/sand BGC* Other

DETAILS:

Pipe Type: Cast Iron Ductile Iron Steel PCCP Plastic
 Pipe Size: 8"
 Repair Method: Clamp Weld Cut Other

DETAILS:



Form of Break: Circular Longitudinal Other

DETAILS:

PHOTO AFTER REPAIRS:

Number of Pictures: 1

SKETCH OF SITE



* BGC = blue/gray clay