

Howard County Pipe Break Field Data

Location and Contact information			
Date	11-21-12	Time	700
Crew Leader name	Ball	Crew Leader phone #	113
Address	6607 St Jean Way		
ADC page		ADC Grid	4936 D10
Base Map #	4	Contract #	950

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Hole

Size of Pipe

Size in inches	8
----------------	---