

Howard County Pipe Break Field Data

Location and Contact information			
Date	5-27-11	Time	12:30 AM
Crew Leader name	Tom Miller	Crew Leader phone #	410-313-4900
Address	6657 Pitch way		
ADC page	4936	ADC Grid	37
Base Map #	24-44	Contract #	950

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

5 Hole in pipe

Size of Pipe

Size in inches	6
----------------	---