

Howard County Pipe Break Field Data

Location and Contact information			
Date 5-10-11	6677 Paul Way	Time 1:00 PM	
Crew Leader name	Dave Bell	Crew Leader phone #	
Address			
ADC page	4936	ADC Grid 4936-E-10	
Base Map #	2444	Contract # 1224	

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

(Hole in pipe)

Size of Pipe

Size in inches	6"
----------------	----