

Howard County Pipe Break Field Data

Location and Contact information			
Date	4-6-12	Time	3.00
Crew Leader name	T. PICKETT	Crew Leader phone #	/
Address	6680 Pind Way		
ADC page	4936	ADC Grid	E-10
Base Map #	37-2444	Contract #	950

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

2- HOLES

Size of Pipe

Size in inches	6"
----------------	----