

Howard County Pipe Break Field Data

Location and Contact information			
Date	6-26-17	Time	10:00
Crew Leader name	D. Ball	Crew Leader phone #	113
Address	6599 6955 Oakland Mill Rd		
ADC page		ADC Grid	
Base Map #		Contract #	1082

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron		PCCP/Concrete	
Ductile iron	<input checked="" type="checkbox"/>	Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Hole in pipe

Size of Pipe

Size in inches	8"
----------------	----