

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 12/1/08
 TIME: 7:00
 TIME OF BREAK: 12:00 11/28/08
 ENGINEER: _____

LOCATION: _____
 GPS LOCATION: 7155 Talisman La

 GPS: S75

PHOTO BEFORE REPAIRS:
 Number of Pictures: N/A

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: Clay Sand Silt Clay/sand BGC* Other

DETAILS:

Pipe Type: Cast Iron Ductile Iron Steel PCCP Plastic
 Pipe Size: 6"
 Repair Method: Clamp Weld Cut Other


DETAILS:

Form of Break: Circular Longitudinal Other

DETAILS:

PHOTO AFTER REPAIRS:

Number of Pictures: N/A



* BGC = blue/gray clay