

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 11/13/09
 TIME: 9:00 AM
 TIME OF BREAK: 4:00 PM
 ENGINEER: Bernie Sensibaugh

LOCATION:
 GPS LOCATION: 8291 Woodward St (Savage)
ABC map - 20-36

GPS: _____

PHOTO BEFORE REPAIRS:

Number of Pictures: N/A

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: Clay Sand Silt Clay/sand BGC* Other

DETAILS:

Sand + Rock Bank on

Pipe Type: Cast Iron Ductile Iron Steel PCCP Plastic

Pipe Size: 12"

Repair Method: Clamp Weld Cut Other


DETAILS:

Form of Break: Circular Longitudinal Other

DETAILS:

PHOTO AFTER REPAIRS:

Number of Pictures: N/A



* BGC = blue/gray clay