

Howard County Pipe Break Field Data

Location and Contact information			
Date	12-22-12	Time	4:00 PM
Crew Leader name	Picketh - Garrett	Crew Leader phone #	
Address	8866 Blade Stream		
ADC page	4935	ADC Grid	J-6
Base Map #	31- 2742	Contract #	479

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	6"
----------------	----