

## Howard County Pipe Break Field Data

Location and Contact information			
Date	4-26-12	Time	7:00
Crew Leader name	D. Ball	Crew Leader phone #	113
Address	8929 Bali Ct N		
ADC page		ADC Grid	
Base Map #		Contract #	12

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

old clamp

### Size of Pipe

Size in inches	6
----------------	---