

Howard County Pipe Break Field Data

Location and Contact information			
Date	11/23/2012	Time	8:00 am
Crew Leader name	Tom Miller	Crew Leader phone #	443-909-8145
Address	9005 Constant course Columbia, Md 21045		
ADC page	5053	ADC Grid	J2
Base Map #	2342	Contract #	3458

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand	x	Blue/gray clay	
Silt	x		

Pipe Type

Type	Check box	Type	Check box
Cast iron		PCCP/Concrete	
Ductile iron	x	Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Pitting	x	Valve problem	
Fitting leak		Clamp repair	

Size of Pipe

Size in inches	8"
----------------	----