

Howard County Pipe Break Field Data

Location and Contact information			
Date	11-11-12	Time	7:00 AM
Crew Leader name	Tom Puchitt	Crew Leader phone #	
Address	9207 Perfect Hour @ INTERSECTION Bush Run		
ADC page	5053	ADC Grid	6-2
Base Map #	2342	Contract #	535

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	6"
----------------	----