

## Howard County Pipe Break Field Data

	Location and Contact information		
Date	12-25-11	Time	10:00 AM
Crew Leader name	Tom Pickett	Crew Leader phone #	
Address	9327 Meadow Hill Dr.		
ADC page	4815	ADC Grid	-E-9
Base Map #	3142	Contract #	229

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

### Size of Pipe

Size in inches	6"
----------------	----