

Section 2




Figure 44 - Results of Stray Current Test #3 on the Access Road near Alpha Ridge Landfill

An unknown event was recorded approximately 22 minutes after the data logger recording started. It is possible that something may have occurred at the TRANSCO Williams ICCP rectifier / ground beds located nearby. The overall pattern of the data in both plots carries the typical signature of stray current gradients associated with operation of DC power.