

Howard County Pipe Break Field Data

Between Baltimore St and Washington St.

Location and Contact information			
Date	<i>11-10-12</i>	Time	<i>7:00 AM</i>
Crew Leader name	<i>Tom Pickett</i>	Crew Leader phone #	
Address	<i>Baldwin St Between Baldwin + Washington</i>		
ADC page	<i>5053</i>	ADC Grid	<i>J-9</i>
Base Map #	<i>Grid 47-1942</i>	Contract #	<i>-3W 3-W</i>

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	<i>6"</i>
----------------	-----------