Howard County Pipe Break Field Data

	Location and Contact information				
Date	11/17/2012		Time	5:00 am	
Crew Leader name	Chuck Garrett		Crew Leader phone #	410-313-4940	
Address	Intersection of commerce center drive and Robert Fulton drive Columbia Md 2104				
ADC page	5053	ADC Grid	J2		

Soil Type

Туре	Check box	Type	Check box
Clay	×	Clay/sand	
Sand		Blue/gray clay	×
Silt	х		

Pipe Type

Туре	Check box	Туре	Check box
Cast iron		PCCP/Concrete	
Ductile iron	×	Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Туре	Check box	Туре	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Pitting	×	Valve problem	
Fitting leak		Clamp repair	

Size of Pipe

Size of Fipe	
Size in inches	12"