

## Howard County Pipe Break Field Data

Location and Contact information			
Date	4-8-12	Time	2:00
Crew Leader name	T PICKETT	Crew Leader phone #	
Address	Dwlan		
ADC page	4936	ADC Grid	E-10
Base Map #	6-37 2444	Contract #	950

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

(HOLE)

### Size of Pipe

Size in inches	6"
----------------	----