Howard County Pipe Break Field Data

	Location and Contact	information			
Date	3-8-11		Time	9	9:00 Am
Crew Leader name	Ton Mills	EF	Crew Leader phone	e# 4	10-313-4900
Address	GOVERNOT W WEST SIDE -: PKWY APROX	SOUTH BOU 300 FT 30	PKWY not LAME OF UTO OF TWIN	GOVETI	not workield
ADC page	4935	ADC Grid		36	
Base Map #	2640	Contract	#	490	Ó

Soil Type

Туре	Check box	Туре	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	-
Silt			

Pipe Type

Туре	Check box	Туре	Check box
Cast iron		PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

. ype or Break			
Туре	Check box	Туре	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size of tipe	
Size in inches	811