

## Howard County Pipe Break Field Data

Location and Contact information			
Date	10/13/2012	Time	7:00 am
Crew Leader name	Chuck Garrett	Crew Leader phone #	410-313-4940
Address	Longview drive & Hickorymede drive		
ADC page	4815	D5	
Base Map #	3341	Contract #	565

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

### Pipe Type

Type	Check box	Type	Check box
Cast iron		PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite	<input checked="" type="checkbox"/>		

### Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Pitting		Valve problem	
Fitting leak		Clamp repair	<input checked="" type="checkbox"/>

### Size of Pipe

Size in inches	8"
----------------	----