

Howard County Pipe Break Field Data

Tom Pickett

	Location and Contact information		
Date	9-19-11	Time	2:AM
Crew Leader name	Tom Miller	Crew Leader phone #	
Address	@Mednath Napus Farm Rd.		
ADC page	4934-H4	ADC Grid	29
Base Map #	2739	Contract #	400

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	8"
----------------	----