

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 7-19-09
 TIME: 1:00 PM
 TIME OF BREAK: BLOWN SADDLE - 1 1/2 service
 ENGINEER: _____

LOCATION:
 GPS LOCATION: GRID- 35 - BM- 2639

 GPS: _____

PHOTO BEFORE REPAIRS:
 Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: ___ Clay ___ Sand Silt ___ Clay/sand ___ BGC* ___ Other

DETAILS:

Pipe Type: ___ Cast Iron Ductile Iron ___ Steel ___ PCCP ___ Plastic
 Pipe Size: 6"
 Repair Method: Clamp ___ Weld ___ Cut ___ Other

DETAILS:

Form of Break: ___ Circular ___ Longitudinal ___ Other

DETAILS:

Tom Pickett

PHOTO AFTER REPAIRS:
 Number of Pictures: _____

<p>SKETCH OF SITE</p> <div style="border: 1px solid black; height: 150px; width: 100%;"></div>	<p style="text-align: center;">TESTING VIEW</p> <div style="text-align: center;"> </div>
---	---

* BGC = blue/gray clay