

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 11-30-06
 TIME: 4:00 pm
 TIME OF BREAK: _____
 ENGINEER: _____

LOCATION: _____
 GPS LOCATION: 10369 Blue Arrow Ct.

GPS: 556

PHOTO BEFORE REPAIRS:
 Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	



Soil Type: ___ Clay Sand ___ Silt ___ Clay/sand ___ BGC* ___ Other
DETAILS:

Pipe Type: Cast Iron ___ Ductile Iron ___ Steel ___ PCCP ___ Plastic
 Pipe Size: 8"
 Repair Method: ___ Clamp ___ Weld ___ Cut Other
DETAILS: 8" Hymax 1 Bolt + 8" pipe D.I.

Form of Break: ___ Circular ___ Longitudinal Other
DETAILS: Hole in pipe

PHOTO AFTER REPAIRS:
 Number of Pictures: _____

SKETCH OF SITE



* BGC = blue/gray clay