

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 12-23-05
TIME: 8:00 am
TIME OF BREAK: 7:30 am
ENGINEER: G. Gibson

LOCATION:

GPS LOCATION: 3712 Font Hill Drive

GPS: 499 us

PHOTO BEFORE REPAIRS:

Number of Pictures:

SOIL CHEMISTRIES:

REDOX	SOIL BOX RESISTIVITIES	pH
(mV)	(Ohm-cm)	(mV)
(mV)	(Ohm-cm)	(mV)
Top of Pipe (12)	Top of Pipe (12)	Top of Pipe (12)
Side of Pipe (3 / 9)	Side of Pipe (3 / 9)	Side of Pipe (3 / 9)
Bottom of Pipe (6)	Bottom of Pipe (6)	Bottom of Pipe (6)
		Actual Soil pH

Soil Type: Clay Sand Silt Clay/sand BGC* Other

DETAILS:

Pipe Type: Cast Iron Ductile Iron Steel PCCP Plastic

Pipe Size: 8"

Repair Method: Clamp Weld Cut Other

DETAILS:

Form of Break: Circular Longitudinal Other

DETAILS:

PHOTO AFTER REPAIRS:

Number of Pictures:

<p>SKETCH OF SITE</p> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>	<p style="text-align: center;">TESTING VIEW</p>
---	--

* BGC = blue/gray clay