

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 12-2-03  
 TIME: 2:00 PM  
 TIME OF BREAK: 1:30 PM  
 ENGINEER: \_\_\_\_\_

**LOCATION:**

GPS LOCATION: 10106 La belle CT  
 \_\_\_\_\_  
 \_\_\_\_\_

GPS: 729-W

**PHOTO BEFORE REPAIRS:**

Number of Pictures: \_\_\_\_\_

**SOIL CHEMISTRIES:**

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: \_\_\_ Clay \_\_\_ Sand \_\_\_ Silt  Clay/sand \_\_\_ BGC\* \_\_\_ Other

**DETAILS:**

Pipe Type: \_\_\_ Cast Iron  Ductile Iron \_\_\_ Steel \_\_\_ PCCP \_\_\_ Plastic

Pipe Size: 6"

Repair Method:  Clamp \_\_\_ Weld \_\_\_ Cut \_\_\_ Other

**DETAILS:**

Form of Break: \_\_\_ Circular \_\_\_ Longitudinal  Other

**DETAILS:**

2" Hole In the side of the Pipe

**PHOTO AFTER REPAIRS:**

Number of Pictures: \_\_\_\_\_

**SKETCH OF SITE**

