

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 5-19-04
 TIME: 3:00 pm
 TIME OF BREAK: _____
 ENGINEER: _____

LOCATION: _____
 GPS LOCATION: 6960 LITTLE BOOTS

GPS: _____

PHOTO BEFORE REPAIRS:

Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: ___ Clay Sand ___ Silt ___ Clay/sand ___ BGC* ___ Other

DETAILS:

Pipe Type: ___ Cast Iron ___ Ductile Iron ___ Steel ___ PCCP ___ Plastic AC

Pipe Size: 6"

Repair Method: Clamp ___ Weld ___ Cut ___ Other

DETAILS:

Form of Break: ___ Circular ___ Longitudinal Other



DETAILS:

SADDLE LEAK

PHOTO AFTER REPAIRS:

Number of Pictures: _____

SKETCH OF SITE



* BGC = blue/gray clay