

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 7/2/05

TIME: \_\_\_\_\_

TIME OF BREAK: ~ 18:00 hrs

ENGINEER: M. Hamilton

LOCATION: 3110 Normandy Woods Dr

GPS LOCATION: \_\_\_\_\_

GPS: \_\_\_\_\_

**PHOTO BEFORE REPAIRS:**

Number of Pictures: 1/9

**SOIL CHEMISTRIES:**

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type:  Clay  Sand  Silt  Clay/sand  BGC\*  Other

**DETAILS:**

Pipe Type:  Cast Iron  Ductile Iron  Steel  PCCP  Plastic

Pipe Size: 2"

Repair Method:  Clamp  Weld  Cut  Other

**DETAILS:**



Form of Break:  Circular  Longitudinal  Other

**DETAILS:**

**PHOTO AFTER REPAIRS:**

Number of Pictures: 1/9

**SKETCH OF SITE**



\* BGC = blue/gray clay