

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 11-17-06  
 TIME: \_\_\_\_\_  
 TIME OF BREAK: 6:00 AM  
 ENGINEER: \_\_\_\_\_

LOCATION: \_\_\_\_\_  
 GPS LOCATION: 4001 old Columbia Pike

GPS: 11-W

PHOTO BEFORE REPAIRS:  
 Number of Pictures: \_\_\_\_\_

**SOIL CHEMISTRIES:**

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: \_\_\_ Clay \_\_\_ Sand \_\_\_ Silt  Clay/sand \_\_\_ BGC\* \_\_\_ Other

**DETAILS:**

Pipe Type:  Cast Iron \_\_\_ Ductile Iron \_\_\_ Steel \_\_\_ PCCP \_\_\_ Plastic

Pipe Size: 8"

Repair Method:  Clamp \_\_\_ Weld \_\_\_ Cut \_\_\_ Other

**DETAILS:**


Form of Break:  Circular \_\_\_ Longitudinal \_\_\_ Other HOLE PIPE

**DETAILS:**

**PHOTO AFTER REPAIRS:**

Number of Pictures: \_\_\_\_\_

SKETCH OF SITE



\* BGC = blue/gray clay