

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 5-21-2004
 TIME: 10:00 AM
 TIME OF BREAK: " "
 ENGINEER: _____

LOCATION:

GPS LOCATION: 8072 Red Jacket Way

GPS: _____

PHOTO BEFORE REPAIRS:

Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: ___ Clay Sand ___ Silt ___ Clay/sand ___ BGC* ___ Other

DETAILS:

Pipe Type: ___ Cast Iron Ductile Iron ___ Steel ___ PCCP ___ Plastic

Pipe Size: 8"

Repair Method: Clamp ___ Weld ___ Cut ___ Other

DETAILS:


Form of Break: ___ Circular ___ Longitudinal Other

DETAILS:

PHOTO AFTER REPAIRS:

Number of Pictures: 1/a

SKETCH OF SITE



* BGC = blue/gray clay