

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: Sunday December 26, 2004
 TIME: 11:00 am
 TIME OF BREAK: 12:00 am
 ENGINEER: _____

LOCATION:
 GPS LOCATION: 5499 Sleeping Dog Lane

GPS: _____

PHOTO BEFORE REPAIRS:
 Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	


Soil Type: Clay Sand Silt Clay/sand BGC* Other

Pipe Type: Cast Iron Ductile Iron Steel PCCP Plastic
 Pipe Size: _____
 Repair Method: Clamp Weld Cut Other

Form of Break: Circular Longitudinal Other

PHOTO AFTER REPAIRS:
 Number of Pictures: _____

SKETCH OF SITE



* BGC = blue/gray clay