

Howard County Pipe Break Field Data

| | | | |
|------------------|----------------------------------|---------------------|---------|
| | Location and Contact information | | |
| Date | 12-31-11 | Time | 4:30 PM |
| Crew Leader name | Tom Peckett | Crew Leader phone # | |
| Address | | | |
| ADC page | 4815 | ADC Grid | 6-5 |
| Base Map # | 3342 | Contract # | 216 |

Soil Type

| Type | Check box | Type | Check box |
|------|-------------------------------------|----------------|-----------|
| Clay | | Clay/sand | |
| Sand | | Blue/gray clay | |
| Silt | <input checked="" type="checkbox"/> | | |

Pipe Type

| Type | Check box | Type | Check box |
|--------------|-------------------------------------|----------------------|-----------|
| Cast iron | <input checked="" type="checkbox"/> | PCCP/Concrete | |
| Ductile iron | | Plastic PVC | |
| Steel | | Plastic polyethylene | |
| AC/Transite | | | |

Type of Break

| Type | Check box | Type | Check box |
|--------------|-------------------------------------|------------------|-----------|
| Circular | <input checked="" type="checkbox"/> | Damage by others | |
| Split | | Pipe Joint leak | |
| Fitting leak | | Valve problem | |

Size of Pipe

| | |
|----------------|----|
| Size in inches | 6" |
|----------------|----|