

66020

Entered

TP

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 1-16-11
 TIME: 10:00
 TIME OF BREAK: 9:00
 ENGINEER: T. PICKETT

LOCATION:
 GPS LOCATION: 6011 Capron, WAY
RM
GRID 37- 2444 CONT

GPS: _____

PHOTO BEFORE REPAIRS:

Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: ___ Clay ___ Sand Silt ___ Clay/sand ___ BGC* ___ Other

DETAILS:

Pipe Type: Cast Iron ___ Ductile Iron ___ Steel ___ PCCP ___ Plastic
 Pipe Size: 8"
 Repair Method: ___ Clamp ___ Weld ___ Cut Other

DETAILS:


Replaced section of Pipe 7' of PIPE
 Form of Break: ___ Circular ___ Longitudinal Other

DETAILS:

Bell joint deteriorated, hole in bottom of Pipe

PHOTO AFTER REPAIRS:

Number of Pictures: _____



* BGC = blue/gray clay