

Howard County Pipe Break Field Data

Location and Contact information			
Date	6.24.12	Time	5:30 AM
Crew Leader name	Perkins	Crew Leader phone #	
Address			
ADC page	5053	ADC Grid	C-2
Base Map #	42 / 2341	Contract #	700

Soil Type

Type	Check box	Type	Check box
Clay	<input checked="" type="checkbox"/>	Clay/sand	<input type="checkbox"/>
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	<input type="checkbox"/>
Silt	<input type="checkbox"/>		<input type="checkbox"/>

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input type="checkbox"/>	PCCP/Concrete	<input type="checkbox"/>
Ductile iron	<input type="checkbox"/>	Plastic PVC	<input type="checkbox"/>
Steel	<input checked="" type="checkbox"/>	Plastic polyethylene	<input type="checkbox"/>
AC/Transite	<input checked="" type="checkbox"/>		<input type="checkbox"/>

Type of Break

Type	Check box	Type	Check box
Circular	<input type="checkbox"/>	Damage by others	<input type="checkbox"/>
Split	<input type="checkbox"/>	Pipe Joint leak	<input type="checkbox"/>
Fitting leak	<input checked="" type="checkbox"/>	Valve problem	<input type="checkbox"/>

Size of Pipe

Size in inches	6"
----------------	----

(Blown saddle)