

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 8/14/07
 TIME: 11am
 TIME OF BREAK: _____
 ENGINEER: _____

LOCATION:
 GPS LOCATION: 9571 Washington Blvd

GPS: _____

PHOTO BEFORE REPAIRS:

Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
	(mV)		(Ohm-cm)		(mV)
	(mV)		(Ohm-cm)		(mV)
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: Clay Sand Silt Clay/sand BGC* Other

DETAILS:

Pipe Type: Cast Iron Ductile Iron Steel PCCP Plastic

Pipe Size: 8"

Repair Method: Clamp Weld Cut Other

DETAILS: Drilled.

Form of Break: Circular Longitudinal Other



DETAILS:

5"-6" split

PHOTO AFTER REPAIRS:

Number of Pictures: _____

SKETCH OF SITE



* BGC = blue/gray clay