

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 10-7-06  
 TIME: 11:00 P.M.  
 TIME OF BREAK: \_\_\_\_\_  
 ENGINEER: \_\_\_\_\_

LOCATION: \_\_\_\_\_  
 GPS LOCATION: 6394 WindHarp way

GPS: 486

**PHOTO BEFORE REPAIRS:**

Number of Pictures: \_\_\_\_\_

**SOIL CHEMISTRIES:**

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: \_\_\_ Clay \_\_\_ Sand  Silt \_\_\_ Clay/sand \_\_\_ BGC\* \_\_\_ Other

**DETAILS:**

Pipe Type:  Cast Iron \_\_\_ Ductile Iron \_\_\_ Steel \_\_\_ PCCP \_\_\_ Plastic

Pipe Size: 6"

Repair Method:  Clamp \_\_\_ Weld \_\_\_ Cut \_\_\_ Other

**DETAILS:**


Form of Break:  Circular \_\_\_ Longitudinal \_\_\_ Other

**DETAILS:**


**PHOTO AFTER REPAIRS:**

Number of Pictures: \_\_\_\_\_

**SKETCH OF SITE**



**TESTING VIEW**



\* BGC = blue/gray clay