

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 10-26-04
 TIME: 7:30
 TIME OF BREAK: 11:00 pm 10-25-04
 ENGINEER: _____

LOCATION:
 GPS LOCATION: 5773 Yellow Rose Ct. + High Tor Hill

GPS: _____

PHOTO BEFORE REPAIRS:
 Number of Pictures: . _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12) <input checked="" type="checkbox"/>		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: ___ Clay Sand ___ Silt ___ Clay/sand BGC* ___ Other

DETAILS:

Pipe Type: ___ Cast Iron Ductile Iron ___ Steel ___ PCCP ___ Plastic

Pipe Size: 6

Repair Method: Clamp ___ Weld ___ Cut ___ Other

DETAILS:

Form of Break: Circular ___ Longitudinal ___ Other

DETAILS:

PHOTO AFTER REPAIRS:

Number of Pictures: _____

SKETCH OF SITE	<p style="text-align: center;">TESTING VIEW</p>
-----------------------	--

* BGC = blue/gray clay