

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 015
Location: Harpers Farm Rd. at Eliot Oaks Rd.
Inspection Date: April 12, 2018

Inspection Overall Score: 71

Significant Findings:

Cast iron base plates. NW Corner signal structures has significant rusting and deterioration around the base plate area, anchor bolts, and tightening nuts.



Maintenance Issues:

Crosswalks and Stop Lines are in fair condition.