

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 016  
**Location:** Little Patuxent Parkway at Governor Warfield Parkway  
**Inspection Date:** April 11, 2018

**Inspection Overall Score:** 36

### Significant Findings:

Poles and paint coating in overall fair condition, with small areas of paint coating failure and surface rust beginning to form. Recommend cleaning, prime, and re-paint. South Median structure has significant vehicle impact damage. Structure was evaluated and determined to be ok. Base plate was also buried and had to be dug out.



### Maintenance Issues:

N/A