

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 017

Location: Governor Warfield Parkway at Windstream Way/Columbia Mall

Inspection Date: April 11, 2018

Inspection Overall Score: 48

Significant Findings:

Poles and paint coating in overall fair condition. West median pole has moderate rusting around the base plate area and tightening nuts.



Maintenance Issues:

N/A