

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 022

Location: Little Patuxent Parkway at Columbia Rd.

Inspection Date: February 27, 2018

Inspection Overall Score: 46

Significant Findings:

Poles, and paint coating in overall fair condition. South Median structure had moderate rusting behind the tightening nut caps. Area should be media blasted, prime, and re-painted.



Maintenance Issues:

N/A