

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 037

**Location:** Little Patuxent Parkway at Rouse Parkway/Columbia Mall

**Inspection Date:** April 11, 2018

**Inspection Overall Score:** 66

### Significant Findings:

North Median structure has significant deterioration of the tightening nuts. South Median structure has significant rusting and deterioration of the leveling and tightening nuts, and has vehicle impact damage.



### Maintenance Issues:

N/A