


## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 046  
**Location:** Twin Rivers Rd. at Trumpeter Rd.  
**Inspection Date:** May 1, 2018

**Inspection Overall Score:** 21

### Significant Findings:

Poles are in overall good condition. Paint coating is in good condition, however some peeling is starting to occur on the mast-arm.



### Maintenance Issues:

Crosswalks are in fair condition.  
North Side Pole – loose tightening nuts.