HO-1001

15904 Union Chapel Road, Daisy Private

Description:

The house at 15904 Union Chapel Road is located in Daisy, just east of Daisy Road, in western Howard County, Maryland. It sits on the north side of the road, back from the road, and is a one-story, three -bay by three-bay frame structure with a parged foundation, aluminum siding, and a gable roof with asphalt shingles and an east-west ridge. There is an ell on the front, in the west bay, with a gable roof that has a north-south ridge, and an ell on the rear, in the east bay, that also has a parged foundation, aluminum siding, and a gable roof with asphalt shingles and a north-south ridge. The latter is three bays by two bays. The south elevation has a one-story porch in the center and east bays, with a shed roof with asphalt shingles that is integral with the roof of the main block, but at a different pitch.

Significance:

The house at 15904 Union Chapel Road was reportedly built in 1960, according to the state assessments and taxation office, and there is no reason to believe this date is far off the mark. The building has certain affinities with both bungalows, because of the integral porch, and later Cape Cods, which the main block essentially is. The front ell is a feature that seems to be common in the post-war period and may be primarily a way to add some interest and variety to the façade of a Cape while providing one extra room. The ell on the rear of this building is a later addition. This house represents a common post-war suburban type of domestic architecture in this country, here located in a very small crossroads community, and illustrates the complete abandonment of traditional architecture for national building types by Howard Countians in the twentieth century. It was demolished in late 2009 in order to redevelop the site for commercial purposes.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

1. Name of	Property	(indicate preferred na	ame)		
historic					
other					
2. Location	And number 15904 Union Chapel Road not for publication wn Woodbine X vicinity				
street and number	er 15904 Union C	hapel Road	a .	<u></u>	not for publication
city, town	Woodbine			<u>X</u> _	vicinity
county	Howard				
3. Owner o	f Property	(give names and mailing	addresses of all owne	rs)	
name	Union Chapel I	Partners LLC			
street and number	er 8620 Baltimore	National Pike		telephone	
city, town	Ellicott City		state MD	zip code 2	21043
city, town		→ F/A			umber
Cont Cont Dete Recc Histo	tributing Resource in tributing Resource in tributing Resource in tributing the individual tributing the individual indiv	in National Register District in Local Historic District the National Register/Marylan or the National Register/Maryla ER rt or Research Report at MHT	d Register		
6. Classific	ation				
Category district X building(s) structure site object	Ownershippublic _X_privateboth	Current Function agriculturecommerce/tradedefensedomesticeducationfunerarygovernmenthealth careindustry	landscape recreation/culture religion social transportation work in progress unknown X vacant/not in use other:	0 0 0 1	Noncontributing 1 buildings 0 sites 0 structure 0 objects 1 Total contributing Resources sted in the Inventory

7. D	escription
------	------------

Inventory No. HO- 1001

Condition

_	_ excellent	deteriorated
X	_ good	ruins
	fair	altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

Summary:

The house at 15904 Union Chapel Road is located in Daisy, just east of Daisy Road, in western Howard County, Maryland. It sits on the north side of the road, back from the road, and is a one-story, three -bay by three-bay frame structure with a parged foundation, aluminum siding, and a gable roof with asphalt shingles and an east-west ridge. There is an ell on the front, in the west bay, with a gable roof that has a north-south ridge, and an ell on the rear, in the east bay, that also has a parged foundation, aluminum siding, and a gable roof with asphalt shingles and a north-south ridge. The latter is three bays by two bays. The south elevation has a one-story porch in the center and east bays, with a shed roof with asphalt shingles that is integral with the roof of the main block, but at a different pitch.

Description:

The house at 15904 Union Chapel Road is located in Daisy, just east of Daisy Road, in western Howard County, Maryland. It sits on the north side of the road, back from the road, and is a one-story, three -bay by three-bay frame structure with a parged foundation, aluminum siding, and a gable roof with asphalt shingles and an east-west ridge. There is an ell on the front, in the west bay, with a gable roof that has a north-south ridge, and an ell on the rear, in the east bay, that also has a parged foundation, aluminum siding, and a gable roof with asphalt shingles and a north-south ridge. The latter is three bays by two bays.

The south elevation has a six-over-one sash with brick sill in the front ell, a door with six lights over two panels in the center bay, and a tripartite window with a large picture window flanked by a one-over-one sash on each side. It also has a brick sill. There is a one-story porch in the center and east bays, with a concrete deck, two posts consisting of paired posts with lattice between them, and a shed roof with asphalt shingles that is integral with the roof of the main block, but at a different pitch. The east elevation of the main block has a pair of six-over-one sash in both end bays and the gable end, each with a brick sill. The north bay sash are shorter than the rest. There is a narrow stove chimney between the south bay and gable end windows, and it is covered with aluminum siding.

The east elevation of the rear ell has a door in the south bay that has three lights over three lying panels. There is a small one-over-one sash just north of it, and a similar sash in the center bay. The north bay projects forward of the plane of the east wall and has a one-over-one sash. The south elevation of this projection has a door with three lights over three lying panels. There is a two-bay porch in the south and center bays that has a concrete deck, iron post and railing, and a shed roof that continues the roof of the ell. The north elevation of the ell has two one-over-one sash. The west elevation of this ell has a one-over-one sash in the north bay.

The north elevation of the main block has paired six-over-one sash in the center bay and a single six-over-one sash in the west bay, both with brick sills. The west elevation of the main block has three six-

Inventory No. HO-1001

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Name Continuation Sheet

Number 7 Page 1

over-one sash with brick sills, the east bay sash straddling the main block and the front ell. The gable end has paired six-over-one sash, also with a brick sill.

At the north end of the lot is a large modern garage that is not historic.

o. Significance			Inventory No. HO- 1001	
Areas of Significance	Check and j	ustify below		
agriculture archeology X architecture art commerce communications community planning conservation	economics education engineering entertainment/ recreation ethnic heritage exploration/ settlement	health/medicine industry invention landscape architecture law literature maritime history military	performing arts philosophy politics/government religion science social history transportation other:	
N/A		Architect/Builder N/A		
ites c. 1960				
National Register	N	laryland Register	X not evaluated	
	Areas of Significance agriculture archeology X architecture art commerce communications community planning conservation N/A ates c. 1960	Areas of Significance agricultureeconomicsarcheologyeducation X_architectureengineeringartentertainment/commercecommunicationsethnic heritagecommunity planningconservationexploration/conservationexploration/settlement	Areas of Significance agricultureeconomicshealth/medicineindustry X_architectureengineeringinventionartentertainment/landscape architecturecommercerecreationlawcommunicationsethnic heritageliteraturecommunity planningexploration/maritime historyconservationsettlementmilitary N/A	

Cinnificance

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

The house at 15904 Union Chapel Road was reportedly built in 1960, according to the state assessments and taxation office, and there is no reason to believe this date is far off the mark. The building has certain affinities with both bungalows, because of the integral porch, and later Cape Cods, which the main block essentially is. The front ell is a feature that seems to be common in the post-war period and may be primarily a way to add some interest and variety to the façade of a Cape while providing one extra room. The ell on the rear of this building is a later addition. This house represents a common post-war suburban type of domestic architecture in this country, here located in a very small crossroads community, and illustrates the complete abandonment of traditional architecture for national building types by Howard Countians in the twentieth century. It was demolished in late 2009 in order to redevelop the site for commercial purposes.

9. Major Bibliographical References

Inventory No. HO- 1001

N/A

10. Geographical Data

Acreage of surveyed property	.64 A		
Acreage of historical setting	.64 A		
Quadrangle name	Woodbine	Quadrangle scale:	1:24000

Verbal boundary description and justification

The boundaries consist of the property lines for tax map 13, parcel 56, which encompasses all of the historic structures on the property.


11. Form Prepared by			
name/title	Ken Short		
organization	Howard County Department of Planning & Zoning	date	December 2009
street & number	3430 Courthouse Drive	telephone	410-313-4335
city or town	Ellicott City	state	Maryland

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust DHCD/DHCP 100 Community Place Crownsville, MD 21032-2023 410-514-7600



HO-1001

15904 Union Chapel Road Woodbine quad

15904 Union Chapel Road Howard County, Maryland Ken Short, photographer

Photo Log

Nikon D-70 camera HP Premium Plus paper HP Gray Photo print cartridge

HO-1001_2009-11-23_01 South & east elevations

HO-1001_2009-11-23_02 North & west elevations



HO-1001 15904 Union Chapel Rd Howard County, MD Ken Short Nov. 23, 2009 MD SHPC South & East Elevations



HO-1001 15904 Union Chapel Road Howard County, MD Ken Short Nov. 23, 2009 MD SHPO North & West Elevations

