HO-1016 Forest Diner 10031 Baltimore National Pike Private

Description:

The Forest Diner is located on the south side of the road near Ellicott City in eastern Howard County, Maryland. The Diner is a one-story, eleven-bay by seven-bay frame structure with an uneven gable roof that has asphalt shingles, an east-west ridge, and a longer slope on the north side. There is a three-bay by five-bay frame wing on both the east and west ends, and they are set back two bays from the front of the main block and have a lower roof with the same profile as the main block. The north elevation has a stone ashlar planter box across the front, with concrete wall below eleven six-over-one sash and T1-11 siding above the windows. There are canvas awnings around the north, east, and west sides of the building. Above the north awning is a red neon sign, and there is red neon around the edge of the eaves. The west wing also has six-over-one sash, and there is brick veneer at the north end. The entrance is double doors in the north bay of the west elevation of the main block. The east wing is covered by modern decks, mechanical equipment, ducts, awnings, and an exterior brick chimney. The south elevation has a CMU wall on the bottom half with T1-11 siding above. The east end has mechanical equipment added and a shed-roofed frame addition with no openings.

Significance:

The Forest Diner was opened in 1946 by Bob Gearhart who placed a 40-seat dining car on the property, and it was named Gearhart's Diner at that time. In 1957 the diner was sold to William Carl Childress, who apparently started the Forest Motel next door in 1960, and the name was probably changed around that time. The present state of the diner reflects the move of the traditional road-side diner from a traditional stainless steel trailer to a more permanent building in contemporary materials. This transition seems to have occurred in the 1960s and 1970s, before a backlash brought back the stainless steel diner. This building has little or no architectural significance, but has social significance as a traditional eatery and meeting place for Howard Countians and is typical of such institutions prior to the rapid growth of upscale Columbia. The Forest Diner is scheduled to be demolished in a few years for redevelopment of the site.

historic	Forest Diner									
other										
2. Location										
street and number	10031 Baltimo	ore National Pik	e					-	not	for publication
city, town	Ellicott City							2	X_ vici	nity
county	Howard									
3. Owner of	Property	(give name	es and mailing	address	es of al	l owners)				
name	Bonnie Brancl	n Corporation								
street and number	4100 College	Avenue					telepho	one		
city, town	Ellicott City			state	MD		zip coo	de	2104	3
4. Location	of Legal I	Description	5n							
4. Location						liber	11335	folio	618	

- _____ Determined Eligible for the National Register/Maryland Register
- Determined Ineligible for the National Register/Maryland Register
- Recorded by HABS/HAER
- _____ Historic Structure Report or Research Report at MHT
- _____ Other:___

6. Classification

Ownership **Current Function Resource Count** Category district public agriculture landscape Contributing Noncontributing _building(s) X private X commerce/trade _recreation/culture Х 0 buildings 1 structure both defense religion 0 0 sites site domestic social 0 0 structures object education transportation 0 0 objects funerary work in progress 1 0 Total government unknown health care **Number of Contributing Resources** vacant/not in use industry other: previously listed in the Inventory 0

Inventory No. HO-1016

7. Description

Condition

excellent	deteriorated
X_good	ruins
fair	altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

The Forest Diner is located at 10031 Baltimore National Pike, on the south side of the road near Ellicott City in eastern Howard County, Maryland. The Diner is a one-story, eleven-bay by seven-bay frame structure with an uneven gable roof that has asphalt shingles, an east-west ridge, and a longer slope on the north side. There is a three-bay by five-bay frame wing on both the east and west ends, and they are set back two bays from the front of the main block and have a lower roof with the same profile as the main block. The north elevation has a stone ashlar planter box across the front, with concrete wall below eleven six-over-one sash and T1-11 siding above the windows. There are canvas awnings around the north, east, and west sides of the building. Above the north awning is a red neon sign, and there is red neon around the edge of the eaves. The west wing also has six-over-one sash, and there is brick veneer at the north end. The entrance is double doors in the north bay of the west elevation of the main block. The east wing is covered by modern decks, mechanical equipment, ducts, awnings, and an exterior brick chimney. The south elevation has a CMU wall on the bottom half with T1-11 siding above. The east end has mechanical equipment added and a shed-roofed frame addition with no openings.

8. Signific	ance			Inventory No. HO-1016
Period	Areas of Significance	Check and j	ustify below	
1600-1699 1700-1799 1800-1899 X 1900-1999 2000-	 agriculture archeology architecture art commerce communications community planning conservation 	 economics education engineering entertainment/ recreation ethnic heritage exploration/ settlement 	 health/medicine industry invention landscape architecture law literature maritime history military 	 performing arts philosophy politics/government religion science social history transportation other:
Specific dates	N/A		Architect/Builder unkn	lown
Construction da	ates c. 1960-80.			
Evaluation for:				
	National Register	Ν	aryland Register	X not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

The Forest Diner was opened in 1946 by Bob Gearhart who placed a 40-seat dining car on the property, and it was named Gearhart's Diner at that time. In 1957 the diner was sold to William Carl Childress, who apparently started the Forest Motel next door in 1960, and the name was probably changed around that time. The present state of the diner reflects the move of the traditional road-side diner from a traditional stainless steel trailer to a more permanent building in contemporary materials. This transition seems to have occurred in the 1960s and 1970s, before a backlash brought back the stainless steel diner. This building has little or no architectural significance, but has social significance as a traditional eatery and meeting place for Howard Countians and is typical of such institutions prior to the rapid growth of upscale Columbia. The Forest Diner is scheduled to be demolished in a few years for redevelopment of the site.¹

¹ Jennifer Choi and Derek Simmonsen, "Diner's Demise: Over Easy," *Howard County (Maryland) Times*, 19 February 2009, http://www.explorehoward.com/news/15804/diners-demise-over-easy/

9. Major Bibliographical References

See footnotes

10. Geographical Data

Acreage of surveyed property _	.6481 A		
Acreage of historical setting	.6481 A		
Quadrangle name	Ellicott City	Quadrangle scale:	1:24000

Verbal boundary description and justification

The boundaries consist of the property lines for tax map 24, parcel 69, which encompasses all of the historic structures on the property.

11. Form Prepared by


name/title	Ken Short					
organization	Howard County Department of Planning & Zoning	date	February 2010			
street & number	3430 Courthouse Drive	telephone	410-313-4335			
city or town	Ellicott City	state	Maryland			

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust DHCD/DHCP 100 Community Place Crownsville, MD 21032-2023 410-514-7600



HO-1016 Forest Diner 10031 Baltimore National Pike Ellicott City quad

HO-1016 Forest Diner 10031 Baltimore National Pike Howard County, Maryland Ken Short, photographer

Photo Log Nikon D-70 camera HP Premium Plus paper HP Gray Photo print cartridge

HO-1016_2010-01-21_01 East & north elevations

HO-1016_2010-01-21_02 West & south elevations



HO-1016 Forest Diner 10031 Battimore National Pike Howard County, MD Ken Short Jan. 21,2010 MD SHPO East : North Elevations.





HO-1016 Forest Diner 10031 Baltimore National Pike Howard County, MD Ken Short Jan. 21, 2010 MD SHPO West's South Elevations

