

Howard County Pipe Break Field Data

	Location and Contact information		
Date	12-2-11	Time	2:00 pm
Crew Leader name	Tom Miller	Crew Leader phone #	410-313-4900
Address	10124 ROVEOUT LA		
ADC page	5053	ADC Grid	C-2
Base Map #	23-40	Contract #	700

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

Pipe Type

Type	Check box	Type	Check box
Cast iron		PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite	<input checked="" type="checkbox"/>		

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

SADDLE LEAK W.H.C. ✓

Size of Pipe

Size in inches	6"
----------------	----